




Exterior Window & Balcony Door Thermographic Inspections



001_Exterior Window




001_Exterior Window



002_Exterior Window



002_Exterior Window




003_Exterior Window



003_Exterior Window


Exterior Window & Balcony Door Thermographic Inspections



004_Exterior Window




004_Exterior Window



005_Exterior Window



005_Exterior Window




006_Exterior Window



006_Exterior Window

Exterior Window & Balcony Door Thermographic Inspections



007_Exterior Window




007_Exterior Window



008_Exterior Window



008_Exterior Window




009_Exterior Window



009_Exterior Window


Exterior Window & Balcony Door Thermographic Inspections



010_Balcony Door




010_Balcony Door



011_Balcony Door



011_Balcony Door



012_Balcony Door



012_Balcony Door